

No. 1823027

INSPECTION REPORT (ROAD ROLLER)

Model	BW123AC
S/No.	220501
Hour/Km	
Eng. Model	K4F-D
Eng.No.	18094

Eikoh Trading Inc.

Tel 81-45-453-5671

Fax 81-453-1488

Mail enews@etinc.co.jp

Date Jul. 9, 2018

Name Yamaguchi

Cabin/Canopy

Air Condition No

Drive System All wheel drive

General Condition

*Normal working condition
has some crack on anti-vibration rubber*

Engine	<u>Normal working condition</u>	
Exhaust		
Blow-by		
Oil		
Coolant		
Electric		

Tire	Left	Right
Front Drum	<u>about 60%</u>	<u>about 60%</u>
Rear Tire	<u>"</u>	<u>"</u>

Brake Normal working condition

Travel
Parking

Hydraulic	<u>Normal working condition</u>	
Main pump		
Oil cooler		
Cylinder		

Appearance/Interior Fair

Computer
Instrument board
Others

Transmission Normal working condition