

NO. 1823064

**INSPECTION REPORT (BULLDOZER)**

Model	CD5PB
S/No.	611-6597
Hour/Km	stopped at 807
Eng. Model	S4E
Eng.No.	052345

**Eikoh Trading Inc.**

Tel 81-45-453-5671

Fax 81-453-1488

Mail [enews@etinc.co.jp](mailto:enews@etinc.co.jp)

Date Dec.25,2018

Name Yamaguchi

Shoe triangle

Cabin/Canopy

Air Condition NO

Transmission DD-PS

Blade Type PAT

**General Condition**

Normal working condition  
 No mechanical problem  
 1pc. bottom roller broken, front idler adjust cylinder welded

Engine	<u>Normal working condition</u>	
Exhaust		
Blow-by		
Oil		
Coolant		
Electric		

Work Equipment	<u>Fair, Normal working</u>	
Blade		
Frame		
Attachment		

Hydraulic	<u>Normal working condition</u>	
Main pump		
Oil cooler		
Travel		
Cylinder		

Under Carriage	<u>Left 65%</u>	<u>Right 65%</u>
Shoe		
Link		
Bushing		
Sprocket		
Top roller		
Bottom roller		<u>1pc. broken</u>
Idler	<u>Adjust cylinder welded</u>	

Transmission Normal working condition

Appearance/Interior	<u>Painted in Blue color</u>	
Computer		
Instrument board		
Others		

