

NO. 1823065

**INSPECTION REPORT (WHEEL LOADER)**

Model	507
S/No.	51605
<del>Hour</del> /Km	3850
Eng. Model	4094-2
Eng.No.	44909

Eikoh Trading Inc.

Tel 81-45-453-5671 Fax 81-453-1488

Mail [enews@etinc.co.jp](mailto:enews@etinc.co.jp)

Date Jan. 30, 2019

Name Yamaguchi

Tire Size

Cabin/Canopy Nothing

Air Condition No

Drive System F2/R1

Bucket Size

**General Condition**

*Black exhaust gas come out of engine  
 Parking brake doesn't work  
 others are in normal working condition*

Engine	
Exhaust	<i>Black exhaust gas come out</i>
Blow-by	
Oil	
Coolant	
Electric	

Work Equipment		<i>Fair</i>
Bucket		
Arm		
Link		

Hydraulic		<i>Normal working condition</i>
Main pump		
Oil cooler		
Cylinder		

Tire	Left	Right
	Front	<i>65% good</i>
	Rear	<i>"</i>

Transmission *Normal working condition*

Brake	
Travel	<i>Normal working condition</i>
Parking	<i>Doesn't work</i>

Appearance/Interior		<i>Fair</i>
Computer		
Instrument board		
Others		

